

CONTRACER CV-3200/4500 SERIES

HIGH-ACCURACY CONTOUR MEASURING MACHINE WITH EXCITING NEW FEATURES






CONTRACER CV-4500 Series




Continuous top-bottom measurement function for easy measurement of upper and lower surfaces

Upper and lower surfaces can be measured continuously by using Mitutoyo's double-sided conical stylus. This continuous measurement data can be used to facilitate analysis of features that were difficult to measure before, such as the effective diameter of an internal screw-thread.



Variable measuring force function

The measuring force can be varied in 5 steps by using the software provided (FORMTRACEPAK), eliminating the need to adjust the measuring force by switching weights or through positional adjustment. The CV-4500 Series can also maintain the specified measuring force even when tilted.






New Top-bottom Continuous Measurement and Variable Measuring Force.

Detector with new arm design

Expands measurement range while reducing workpiece interference Mitutoyo's newly designed detector arm lowers workpiece interference while expanding the measurement range in the Z1-axis (detector).

• When using the SPH-71 one-sided cut stylus






Detector measurement range expanded by 10 mm


One-touch arm attachment

(Patent pending in Japan)

The arm mount uses a magnetic joint for quick and easy arm replacement. The mount also includes a safety mechanism.

• CV-4100 (Conventional product) • CV-4500





All detector and drive unit cables are housed inside the main unit to eliminate any risk of abrasion and guarantee trouble free, high-speed operation.






Auto stop feature assures safety even during highspeed movement

The detector includes a safety mechanism (auto stop upon collision) to assure measurement safety even during high-speed movement. If the arm is removed or shifts during measurement, the safety mechanism is triggered and stops the machine.



Continuous top-bottom measurement allows hasslefree-one-step-calibration (Patent pending in Japan)

The one-step calibration kit supplied with the CV-4500 Series has been upgraded to enable easy calibration of the double-sided conical stylus featuring a contact on both the top and the bottom. Fiddly work such as calibrating the Z1-axis gain, symmetry, and stylus radius can now be carried out in a single operation.



Best-in-class-displacement accuracy

The CV-4500 Series features a built-in precision arc scale on the Z1-axis (detector) that allows the arc trajectory of the stylus tip to be read directly, minimizing the detector mechanism error and enabling precision, high-resolution measurement. On the X-axis (driver) is a linear scale, allowing high-accuracy full-stroke measurement.

Z1-axis (detector unit) : \pm (0.8 + 0.02H) μ m

H = Measurement height from the horizontal

position (mm)

X-axis (drive unit) : \pm (0.8 + 0.01 L) μ m*¹

L = drive length (mm)

Z1-axis (detector unit) : $0.02 \mu m$ X-axis (drive unit) : $0.05 \mu m$

^{*1} These specifications apply to the CV-4500S4/H4/W4. For specifications of other products in the series, see specifications on page 14.




CONTRACER CV-3200 Series




Detector with new arm design

Expands measurement range while reducing workpiece interference Mitutoyo's newly designed detector arm lowers workpiece interference while expanding the measurement range in the Z1-axis (detector).

• When using the SPH-71 one-sided cut stylus






Detector measurement range expanded by 10 mm


One-touch arm attachment

(Patent pending in Japan)

The arm mount uses a magnetic joint for quick and easy arm replacement. The mount also includes a safety mechanism.

• CV-3100 (Conventional product)





All detector and drive unit cables are housed inside the main unit to eliminate any risk of abrasion and guarantee trouble free, high-speed operation.





Auto stop feature assures safety even during highspeed movement

The detector includes a safety mechanism (auto stop upon collision) to assure measurement safety even during high-speed movement. If the arm is removed or shifts during measurement, the safety mechanism is triggered and stops the machine.



Hassle-free one-step calibration

The CV-3200 Series provides a dedicated calibration gage that lets you carry out fiddly work such as calibrating the Z1-axis gain, symmetry, and stylus radius in a single operation. Calibration of upward measurement is also possible by using Mitutoyo's optional calibration stage.

Calibration kit for CV-3200 series



Best-in-class displacement accuracy

The CV-3200 Series features a built-in precision arc scale on the Z1-axis (detector) that allows the arc trajectory of the stylus tip to be read directly, minimizing the detector mechanism error and enabling precision, high-resolution measurement. On the X-axis (driver) is a linear scale, allowing high-accuracy full-stroke measurement.

Z1-axis (detector unit): $\pm (1.4 + 0.02H) \mu m$

H = Measurement height from the horizontal

position (mm)

 \pm (0.8 + 0.01 L) μ m*¹ X-axis (drive unit):

L = drive length (mm)

Resolution -

Z1-axis (detector unit): 0.04 µm X-axis (drive unit): $0.05 \, \mu m$

^{*1} These specifications apply to the CV-3200S4/H4/W4. For specifications of other products in the series, see specifications on page 14



Efficient Functions Featured by CV-4500 and CV-3200.

Excellent operability

Remote-control unit enables safe, easy & fast measurement

The remote-control unit lets you move quickly from positioning to measurement. The unit also features an emergency stop switch and speed control knob for added safety while the machine is moving at high speeds.



New remote control box

Remarkable Ease of Operation

Incorporation of an ABS scale in the Z2-axis eliminates the need for wearisome origin point re-setting conventionally required for every step of repeated measurements over stepped or multiple sections.



Simple positioning by fine feed mechanisms

Small holes and inclined planes can be efficiently measured using the inclined X-axis drive unit and fine-feed handles on the X- and Z2-axes.



Fast traverse improves measurement efficiency

X-axis (drive unit) : 80 mm/s (MAX) Z2-axis (column) : 30 mm/s (MAX)


The total measurement time can be shortened by speeding up the traverse movements.



Simplified CNC Function

With the support for a wide range of optional peripherals designed for use with the CNC Form Measuring Unit enables simplified CNC measurement.


• *⊕*1-axis rotary unit: Automatic circular-movement






• Θ 2-axis rotary unit: Automatic multiple-section continuous measurement







Contour Analysis Software: FORMTRACEPAK



Multiple languages support (17 languages)

You can switch the language* to be used in the measurement, analysis, and layout windows. After measurements have been made, you can switch to another language and create a report in that language. This function can be used worldwide.

* Supported languages: Japanese, English, German, French, Italian, Spanish, Polish, Hungarian, Swedish, Czech, Simplified Chinese, Traditional Chinese, Korean, Turkish, Portuguese, Danish, Russian.

Online help function*

Online help that can be viewed any time is incorporated into the software. In addition to index and keyword searches, a status saving help button, which displays menus and Windows help with a click of the mouse, is provided.



* Online help function supports only Japanese and English

Measurement control

To make only a single measurement, you can create a part program in the single mode. To measure multiple workpieces of an identical shape, you can use the teaching mode.

FORMTRACEPAK supports the new top-bottom continuous measurement and variable measuring force functions of the CV-4500 Series (see page 2 for details), providing an even higher level of usability. Since you can embed the entire flow, from making measurement to printing a report, into a part program, you can efficiently make measurements, analyse data, and output a report. A function is also provided that enables you to insert comments accompanied with photographs at desired timings, enabling you to embed the roles described in a measurement procedure document that specifies important points such as work settings.



To make immediate measurements, you can use the pull-down menu to easily select and call up the desired operating procedure.



Button-editing function

You can hide buttons that are not used frequently. For example, you can choose to display only those buttons that are used frequently and increase the size of the displayed graphics window, thereby customizing the window to suit your needs.



Simple statistical commands

You can perform statistical calculations of roughness parameters and contour analysis results without using a separate program such as Excel®.



FORMTRACEPAK Functions Offer Total Support.

Contour analysis

Contour analysis function

A wide variety of commands, which form the basic elements for analysis, are provided, including those for points (10 kinds), lines (6 kinds), and circles (6 kinds). A rich set of commands that combine these elements to calculate angles, pitches, and distances, a contour tolerancing function, and a design value generation function are also provided as standard features. These functions, combined with the function that allows you to customize the calculation command buttons by hiding less frequently used commands, let you tailor the window according to the user environment.

Coolings Age Call Dog Cree Co

Removal of abnormal points function


Irregular defects in the data are filtered out from the calculation. This function can effective when specifying the calculation range for locations at which the boundary between circle and line is difficult to determine.

Text output of the calculation result and graphics data

You can output the calculation result as text (in csv or txt format), output graphics data obtained from measurements as point-string data to a text file or CAD file (in the DXF or IGES format), or copy the data to the clipboard. Combined with commercial document or statistical processing software, this feature can be used to share data with computers that do not have dedicated analysis software installed or execute CAD-based reverse engineering.

Simple pitch calculation function


You can efficiently analyse the pitch between identical shapes, such as a screw pitch or the distance between circles (center-to-center pitch), by simply specifying the desired range using mouse operations.




Example of range specification for screw thread pitch with rectangular tool.

Contour-tolerancing function as a standard feature

The best-fit processing function that moves the coordinate values of the design data and measurement data to the optimum positions is provided as a standard feature. Since the tolerancing results can be visually displayed as graphics, displayed as tolerance values and tolerance expansions in each coordinate, or output as a text file, they can be utilized as feedback data for machining systems.



Example of contour-tolerancing result



Example of contour tolerancing results output as numeric values



Contour Analysis Software: **FORMTRACEPAK**


Contour analysis

Design value generation function

You can generate design data from CAD data (DXF or IGES file) or text data. Furthermore, since you can also convert measurement data into design data, you can save parts data prior to use (testing) as design data and effectively utilize it for checking the wear following use (testing).


Data combination function

You can combine partial data collected separately from a workpiece (made necessary due to shape characteristics) into a single graphic for convenient analysis.




Calculation command repetition setting

When identical shapes have the same pitch, you can analyse all of the shapes in a batch by specifying a single analysis location and the pitch.



Best-fit processing function for measurement point strings

This function tries to fit the measurement points to the stored reference data on the same coordinate system. It can eliminate the effects of a shift that may occur when setting the workpiece during automatic analysis.




- [1] Measured points/
- [2] Bestfit reference data/

- [4] Reference coordinate system/ [5] Measurement coordinate system

Data superimposition command

You can superimpose two sets of data by detecting their characteristic points. Use the mouse to drag and move the measurement point strings to the desired positions to be superimposed.








Measurement System Control, Contour Analysis, Contour Tolerancing, and Inspection Report Creation.


Integrated layout

You can use simple operations to lay out graphics obtained from measurements as well as measurement results for surface roughness, contour, and roundness on a single page.

Furthermore, since the program now allows you to specify a saved file and paste it, you can easily paste results from multiple files.

Note: the optional ROUNDPAK roundness/cylindricity analysis program is required. (Ver. 7 or higher)





This bar displays the attribute values of the pasted items, allowing you to easily check the contents of the pasted measurement data files.

System layout printing

By simply selecting the items to be output, you can automatically lay out the page to be printed.

Use this feature when you wish to simplify the printing task.



Element insertion bar

Using the mouse to drag and drop the analysis content displayed in the element insertion bar, you can paste it into the layout. From the contour analysis result, you can also select the analysis result for a circle or line alone and paste it in position.

Saving the result as a web page

Since you can save the result in html or mhtml format, which can be displayed using Internet Explorer® or Microsoft® Word, you can check the result even on a PC on which no layout-editing program is installed.

Report creation function

You can freely assemble measurement results/conditions/graphics as well as comments/circles/lines/arrows, and print them out in a measurement result report. Furthermore, since you can paste bitmap files, you can also add a workpiece image or company logo to the layout. You can also save the created layout and use it again later for similar measurements.

Optional Accessories for Automatic Measurement

Y-axis table: 178-097

Enables efficient, automatic measurement of multiple aligned workpieces and multiple points on a single measurement surface.



Travel range	200 mm
Resolution	0.05 µm
Positioning accuracy	± 3 μm
Drive speed	Max 80 mm/s
Maximum load	50 kg
Mass	28 kg



Rotary table 91-axis table: 12AAD975*

For efficient measurement in the axial/transverse directions. When measuring a cylindrical workpiece, automatic alignment can be performed in combination with the Y-axis table.

* θ 1-axis mounting plate (12AAE630) is required when directly installing on the base of the CV-3200/4500 series.



Displacement	360°
Resolution	0.004°
Maximum load	12 kg
Rotational speed	Max 10°/s
Mass	7 kg



Rotary table 2-axis unit: 178-078*

You can measure multiple points on a cylindrical workiece and automate front/rear-side measurement.

* θ 2 -axis mounting plate (12AAE718) is required when directly installing on the base of the CV-3200/4500 series.



Displacement	360°
Resolution	0.0072°
Maximum load	4 kg
(loading moment)	(343 N·cm or less)
Rotational speed	Max 18°/s
Mass	5 kg



Centering chuck (ring operated): 211-032

This chuck is useful when measuring small workpieces. You can easily clamp them with its knurled ring.



Retention range	Inner latch	OD: ø 1 - ø 36 mm
	Inner latch	I D: ø 16 - ø 69 mm
range	Outer latch	OD: ø 25 - ø 79 mm
Dimensions		ø 118 × 41 mm
Mass		1.2 kg

Micro-chuck: 211-031

This chuck is suitable for clamping extra-small diameter workpieces (Ø1 mm or less), which cannot be retained with the centering chuck.



Retention range	OD: ø 0.1 - ø 1.5 mm
Dimensions	ø 107 x 48.5 mm
Mass	0.6 kg



Optional Accessories

3-axis adjustment table: 178-047

This table helps make the adjustments required when measuring cylindrical surfaces. The corrections for the pitch angle and the swivel angle are determined from a preliminary measurement and the Digimatic micrometers are adjusted accordingly. A flat-surfaced workpiece can also be leveled with this table. By using Mitutoyo's 3-axis adjustment table, the workpiece can be aligned and leveled easily, simply by following the FORMTRACEPAK guidance. No experience or special expertise is required.





Guidance display when using 3-axis adjustment table





Table and fixture systems



- *1 Required for calibrating upward measurement of CV-3200 series.
- ** Required for calibrating in bulk by mounting straight arm/small-hole stylus arm without using cross-travel table and Y-axis table.

 **3 Required for calibrating in bulk by mounting straight arm/sccentric arm/small-hole stylus arm without using cross-travel table and Y-axis table.



Optional Accessories

Vibration isolators Desk types Desk type*1 No.12AAK110 Monitor arm*2 No.12AAK120 Monitor arm Side table*3 No.12AAL019 Desk Desk Side table Example combination: with side table but Example combination: with monitor arm but no side table*3 (tester and PC not included)

*¹ For models with a product code that ends in **S4**, **S8**, **H4**, or **H8**. Please contact us directly if you require units for models with a product code that ends in **W4** or **W8** (large base models). *² Used together with vibration isolator (No.12AAK110).

no monitor arm (tester and PC not included)

- *3 User to provide a printer rack.

Desktop types

Manually charged pneumatic type*4 No.178-023



Automatically charged pneumatic type*4 No.178-025




Stand for Desktop type External size (W×D×H): $640 \times 470 \times 660$ mm, Mass: 25 kg



^{*4} For models with a product code that ends in **S4**, **S8**, **H4**, or **H8**. Please contact us directly if you require units for models with a product code that ends in **W4** or **W8** (large base models).

Arms

Description	Arm No.	Parts No.	Applicable stylus No.
Straight arm	AB-31*5	12AAM101	SPH-5x, 6x, 7x, 8x, 9x, SPHW*6-56,66,76
Eccentric arm	AB-37	12AAQ762	SPH-5x, 6x, 7x, 8x, 9x, SPHW*6-56,66,76
Small-hole arm	AB-33	12AAM103	SPH-41, 42, 43



Styli

Double-sided conical	CDIDAL EC			
	SPHW-56	12AAM095*2	AB-31, AB-37	20
	SPHW-66	12AAM096	AB-31, AB-37	32
stylus*1	SPHW-76	12AAM097	AB-31, AB-37	48
	SPH-51	354882	AB-31, AB-37	6
	SPH-61	354883	AB-31, AB-37	12
One-sided cut stylus	SPH-71	354884 *2*3	AB-31, AB-37	20
	SPH-81	354885	AB-31, AB-37	30
	SPH-91	354886	AB-31, AB-37	42
	SPH-52	354887	AB-31, AB-37	6
Intersecting cut	SPH-62	354888	AB-31, AB-37	12
stylus	SPH-72	354889	AB-31, AB-37	20
stylus	SPH-82	354890	AB-31, AB-37	30
	SPH-92	354891	AB-31, AB-37	42
	SPH-53	354892	AB-31, AB-37	6
Cone stylus	SPH-63	354893	AB-31, AB-37	12
Tip angle 30°	SPH-73	354894	AB-31, AB-37	20
Sapphire tipped	SPH-83	354895	AB-31, AB-37	30
	SPH-93	354896	AB-31, AB-37	42
	SPH-56	12AAA566	AB-31, AB-37	6
Cone stylus	SPH-66	12AAA567	AB-31, AB-37	12
Tip angle 30°	SPH-76	12AAA568	AB-31, AB-37	20
Carbide-tipped	SPH-86	12AAA569	AB-31, AB-37	30
	SPH-96	12AAA570	AB-31, AB-37	42
	SPH-57	12AAE865	AB-31, AB-37	6
Cone stylus	SPH-67	12AAE866	AB-31, AB-37	12
Tip angle 20°	SPH-77	12AAE867	AB-31, AB-37	20
Carbide-tipped	SPH-87	12AAE868	AB-31, AB-37	30
	SPH-97	12AAE869	AB-31, AB-37	42
Cone stylus Tip angle 50° Diamond tipped	SPH-79	355129	AB-31, AB-37	20
	SPH-54	354897	AB-31, AB-37	6
	SPH-64	354898	AB-31, AB-37	12
Knife edge stylus	SPH-74	354899	AB-31, AB-37	20
, , , , , , , , , , , , , , , , , , ,	SPH-84	354900	AB-31, AB-37	30
	SPH-94	354901	AB-31, AB-37	42
	SPH-55	354902	AB-31, AB-37	6
	SPH-65	354903	AB-31, AB-37	12
Ball stylus	SPH-75	354904	AB-31, AB-37	20
-	SPH-85	354905	AB-31, AB-37	30
	SPH-95	354906	AB-31, AB-37	42
	SPH-41	12AAM104	AB-33	2
Small hole stylus*4	SPH-42	12AAM105	AB-33	4
	SPH-43	12AAM106	AB-33	6.5

Double-sided conical stylus Cone stylus






Tip angle: 30° Tip radius: 25 μm Carbide-tipped



Tip angle: 30° (SPH-79: 50°) Tip radius: 25 µm Sapphire, Carbide-tipped (SPH-79: Diamond tipped)

Small hole stylus SPH-41



One-sided cut stylus






Cone stylus

Tip angle: 20° Tip radius: 25 μm Carbide-tipped

Small hole stylus SPH-42



Intersecting cut stylus





Tip radius: 25 µm Carbide-tipped


Tip angle: 20° Tip radius: 25 μm Carbide-tipped

Knife edge stylus



Tip angle: 20° Edge width: 3 mm Tip radius: 25 µm Carbide-tipped

Small hole stylus SPH-43



Ball stylus





Ball dia: 1 mm Carbide-tipped

- *¹ Stylus for CV-4500 series
 *² Standard accessory of CV-4500 series
 *³ Standard accessory of CV-3200 series
 *⁴ Styli SPH-21, 22, and 23 for CV-3100/4100 series are not available.


Arm stylus (comprising an arm and stylus)


Arm stylus name	Stylus No.	Parts No.	H (mm)
Davids aided and I hala and atduct	SPHW-31	12AAM108	2.4
Double-sided small hole arm stylus*5 (Cone 30°)	SPHW-32	12AAM109	5
	SPHW-33	12AAM110	9

*5	Arm Stylus f	or CV-4500 series	
----	--------------	-------------------	--

Arm stylus name	Stylus No.	Parts No.	H (mm)
Double-sided small hole arm stylus*5	SPHW-21	12AAT469	2.4
(Cone 20°)	SPHW-22	12AAT470	5

^{*5} Arm Stylus for CV-4500 series










Specifications

Model			CV-3200S4	CV-3200H4	CV-3200W4	CV-3200L4	CV-3200S8	CV-3200H8	CV-3200W8	CV-3200L8
	Model		CV-4500S4	CV-4500H4	CV-4500W4	CV-3200L4	CV-4500S8	CV-4500H8	CV-4500W8	CV-4500L8
Measuring range	X-axis			100	mm			200	mm	
ivicasuring range	Z1-axis (detector i	unit)	60 mm (± 30 mm in horizontal situation)							
Z2-axi	s (column) travel range		300 mm	500	mm	700 mm	300 mm	500	mm	700 mm
	Scale unit					Arc	scale			
	Resolution		CV-3200series : 0.04 μm, CV-4500series : 0.02 μm							
	Stylus up/down motion		Arc movement							
Detector (Z1-axis (detector unit))	Measuring direction				Вс	th pulling and p	oushing direction	ons		
	Measuring face dire	ection		CV-4500 seri	es : Both upwar		rd (direction sw	itch from FOR	MTRACEPAK)	
	Measuring force	e		CV-4500 se	CV-320 eries: 10, 20, 30	00 series: 30 m 0, 40, 50 mN (S			TRACEPAK)	
	Stylus traceable ra	inge		Asce	nt 77°, Descent	83° (with one-	sided cut stylus	: standard acce	ssory)	
	6 1 ''	X-axis		,		Separate type	linear encoder			
	Scale unit	Z2-axis (column)				ABS e	ncoder			
		X-axis				0.05	μm			
	Resolution	Z2-axis (column)				1	m			
Drive unit		X-axis			0	- 80 mm/s and	manual operati	on		
Drive driit	Drive speed	Z2-axis (column)		0 - 30 mm/s and manual operation						
	Measuring speed	X-axis		0.02 - 5 mm/s						
	Straightness (when the X- axis is horizontal)	X-axis	0.8 μm/ 100 mm				2 μm/ 200 mm			
	X-axis inclination angle	X-axis	± 45°							
	CV-3200 Series	X-axis		3 + 0.01 L) µm Wide range: 1 Narrow range: 1	.8 μm/100 mm			Wide range: 4	L = Drive length .8 μm/ 200 mm 1.3 μm/ 25 mm	
Accuracy	Series	Z1-axis		± (1.4	+ 0.02H) µm H	H = Measurement height from the horizontal position			oosition	
(20°C)	CV-4500 Series	X-axis		3 + 0.01 L) μm Wide range: 1. Narrow range:	8 µm/ 100 mm			Wide range: 4	L = Drive length .8 µm/ 200 mm 1.3 µm/ 25 mm	
	Series	Z1-axis		± (0.8 ·	+ 0.02H) µm H	H = Measureme	nt height from	the horizontal	position	
External	Main unit		756 × 482 × 966 mm	756 × 482 × 1166 mm	1156 x 482 x 1176 mm	1156 x 482 x 1436 mm	766 × 482 × 966 mm	766 x 482 x 1166 mm	1166 x 482 x 1176 mm	1166 × 482 × 1436 mm
dimensions (W×D×H)	Controller		221 x 344 x 490 mm							
(VVXDXII)	Remote box		248 × 102 × 62.2 mm							
	Main unit		140 kg	150 kg	220 kg	270 kg	140 kg	150 kg	220 kg	270 kg
Mass	Controller		14 kg							
	Remote box					0.9	kg			
Opera	ing temperature range			15 - 25°C	(within ± 1K te	mperature fluct	tuation on calib	ration and mea	surement)	
Oper	Operating humidity range			20 - 80% RH (with no condensation)						
Stora	ge temperature range		–10 to 50°C							
Sto	Storage humidity range			5 - 90% RH (with no condensation)						



Dimensions



The CV-3200 series detector comes with weights for adjusting the measuring force.

CV-3200S8/H8/W8/L8, CV-4500S8/H8/W8/L8 **60** [460] 200 178 854 (1054) [1054] {1314} 966 (1166) [1176] [1436] 20 486 : CV-3200S8, CV-4500S8 (): CV-3200H8, CV-4500H8 []: CV-3200W8, CV-4500W8 [200] {}: CV-3200L8, CV-4500W8 mm (200)300 T-groove Mitutoyo 9 46 \oplus 85 igoplusMeasuring range 175 156 130 12 **600** [1000] 450 166 32

The CV-3200 series detector comes with weights for adjusting the measuring force.



Whatever your challenges are, Mitutoyo supports you from start to finish.

Mitutoyo is not only a manufacturer of top quality measuring products but one that also offers qualified support for the lifetime of the equipment, backed up by comprehensive services that ensure your staff can make the very best use of the investment.

Apart from the basics of calibration and repair, Mitutoyo offers product and metrology training, as well as IT support for the sophisticated software used in modern measuring technology. We can also design, build, test and deliver bespoke measuring solutions and even, if deemed cost-effective, take your critical measurement challenges in-house on a sub-contract basis.



Find additional product literature and our product catalogue

www.mitutoyo.eu

Note: Product illustrations are without obligation. Product descriptions respectively capability characteristics are only binding when explicitly agreed upon.

MITUTOYO, CONTRACER and ABSOLUTE are either registered trademarks or trademarks of Mitutoyo Corp. in Japan and/or other countries/regions. Microsoft and Internet Explorer are either registered trademarks or trademarks of Microsoft Corporation in the United States and/or other countries. Other product, company and brand names mentioned herein are for identification purposes only and may be the trademarks of their respective holders.



Mitutoyo Europe GmbH

Borsigstraße 8-10 41469 Neuss

Tel. +49 (0) 2137-102-0 Fax +49 (0) 2137-102-351

info@mitutoyo.eu www.mitutoyo.eu